

TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

1234 Sunshine Road,
INSPECTED ADDRESS

Pleasantville
CITY

TX
STATE

76182
ZIP

SCOPE OF INSPECTION

- A. This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guesthouses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report.
B. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall covers, floor coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.
C. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure(s) being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment; has rendered the pest(s) inactive.
D. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present.
E. If visible damage is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified expert.
F. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS.
G. If termite treatment (including pesticides, baits or other methods) has been recommend, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticide to be used and complete details of warranty (if any). At a minimum, the warranty must specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.
H. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranted, treatment techniques and renewal options.
I. There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended. Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.
J. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Board.

I have read and understand the above SCOPE OF INSPECTION. Buyer's signature: _____

1A. TexInspec, Inc.

Name of Inspection Company

1C. 7510 Davis Blvd. Suite D

Address of Inspection Company

1D. Your Inspector

Name of Inspector (Please Print)

1B. 0570557

SPCS Business License Number

76182

Zip Code

817-265-5452 / 972-231-1945

Phone Number

[X] Certified Applicator

(check one)

[] Technician

2. Job#123456

Case Number (VA/FHA/ Other)

3. Really Soon

Inspection Date

4A. Happy Homeowner

Name of Person Purchasing Inspection

Seller [] Agent [] Buyer [X] Management Co. []

Other []: _____

4B. Unknown

Owner/Seller

4C. Report forwarded to: Title Company or Mortgagee [] Purchaser of service [X] Seller [] Agent [] Buyer []

(Under the Structural Pest Control regulations only the purchaser of the service is required to receive a copy)

The structure(s) listed below were inspected in accordance with the official inspection procedures adopted by the Texas Structural Pest Control board. This report is made subject to the conditions listed under the Scope of Inspection. A diagram must be attached including all structures inspected.

5. Main House Only

List structure(s) inspected that may include residence, detached garages and other structures on the property. (Refer to Part A, Scope of Inspection)

Licensed and Regulated by the Texas Department of Agriculture
P.O. Box 12847, Austin, Texas 78711-2847
Phone (866) 918-4481 Fax (888) 232-2567
(512) 305-8250

TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

6A. Were any areas of the property obstructed or inaccessible? Yes [X] No []

(Refer to Part B & C, Scope of Inspection) If "yes" specify in 6B.

6B. The obstructed or inaccessible areas include but are not limited to the following:

- Attic (Parts of) [X] Insulated area of attic [X] Plumbing areas [X] Planter box abutting structure []
Deck [X] Sub Floors [X] Slab Joints [X] Crawl Space (Parts of) []
Soil Grade Too High [X] Heavy Foliage [] Eaves [X] Weepholes [X]

Other: [X] (Specify): Inside wall voids, under floor coverings, and behind homeowner's belongings

(If the home was occupied during the initial W.D.I., we advise you to engage us to perform a second W.D.I. prior to closing.)

7A. Conditions conducive to wood destroying insect infestation: Yes [X] No []

(Refer to Part I, Scope of Inspection) If "yes" specify in 7B.

7B. Conducive Conditions include but are not limited to:

- Wood to Ground Contact (G) [X] Formboards left in place (I) [] Excessive Moisture (J) [] Debris under or around Structure (K) []
Footing too low or soil line too high (L) [X] Wood Rot (M) [] Heavy Foliage (N) [] Planter Box Abutting Structure (O) []
Wood Pile in Contact With Structure (Q) [] Wooden Fence in Contact with the Structure (R) [X] Insufficient Ventilation (T) []

Other I: [] Specify: _____

(Some of these conditions may be conducive by design and cannot be removed without defacing the property.)

Table with 4 columns: Inspection Reveals visible evidence in or on the structure, Active Infestation, Previous Infestation, Previous Treatment. Rows include Subterranean Termites, Drywood Termites, Formosan Termites, Carpenter Ants, and Other wood Destroying Insects.

8F. Explanation of signs of previous treatment identified: drill marks and treatment notification sticker

8G. Visible evidence of: active sub-termites/previous sub-termites

has been observed in the following areas: front between the two garage doors/rear around the bay window

If there is visible evidence of active or previous infestation, it must be noted. The type of insects(s) must be listed in the first blank and all identified infested areas of the property inspected must be noted in the second blank

(Refer to Part D, E & F, Scope of inspection.)

The conditions conducive to insect infestation reported in 7A & 7B:

9. Will be or has been mechanically corrected by the inspecting company: Yes [] No [X]

If yes, specify corrections: _____

9A. Corrective treatment recommended for active infestation or evidence of previous infestation with no prior treatment as identified in Section 8. (Refer to Part G, H, and I, Scope of inspection) Yes [X] No []

9B. Preventive treatment and/or correction of conducive conditions as identified in 7A & 7B is recommended as follows: Yes [] No [X]

Specify reason: Wood fences and wood decks are conducive by design

Refer to Scope of Inspection Part J (If yes, correction of condition by mechanical means may not be practical.)

10A. This company has treated or is treating the structure for the following wood destroying insects: No

- If treating for subterranean termites, the treatment was: Partial [] Spot [] Bait [] Other []
If treating for drywood termites or related insects, the treatment was: Full [] Limited []

10B. Date of Original Treatment by Inspecting Company N/A

Common Name of Insect N/A Name of Pesticide, Bait or Other Method N/A

This company has a contract or warranty in effect for control of the following wood destroying insects:

Yes [X] No [] List Insects: 90 Day Warranty Termites & Carpenter Ants (\$200 Deductible for Termites \$100 Deductible for Carpenter Ants)

If "Yes", copy(s) of warranty and treatment diagram must be attached.

1234 Sunshine Road,
INSPECTED ADDRESS

Pleasantville
CITY

TX
STATE

76182
ZIP

TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT


The inspector must draw a diagram including approximate perimeter measurements and indicate active or previous infestation and type of insect by the following codes: **E**-Evidence of Infestation: **A** (active), **P** (previous); **D**-Drywood Termite; **S**-Subterranean Termite; **F**-Formosan termite; **C**-Conducive Conditions; **B**- Wood boring Beetles; **H**-Carpenter Ants; Other(s): _____

1234 Sunshine Road,
INSPECTED ADDRESS

Pleasantville
CITY

TX
STATE

76182
ZIP



Additional Comments:

Active sub-termites were noted at the front between the two garage doors and previous sub-termite damage was noted at the rear bay window. Recommend treatment in accordance with TDA standards.

Neither I nor the company for which I am acting have had, presently have, or contemplate having any interest in the property. I do further state that neither I nor the company for which I am acting is associated in any way with any party to this transaction.

Signatures:
 11A. Jonathan Crow **0558673T**
 Inspector
 11B. Jonathan Crow **0558673T**
 Certified Applicator and Certified Applicator License Number

12A. Notice of Inspection Was Posted At or Near:
 Electric Breaker Box:
 Water Heater Closet
 Bath Trap Access
 Beneath Kitchen Sink
 Date Posted: Really Soon

Statement of Purchaser

I have received the original or a legible copy of this form. I have read and understand any recommendations made. I have also read and understand the "Scope of Inspection." I understand that my inspector may provide additional information as an addendum to this report. If additional information is attached, list number of pages: 1

Signature of Purchaser of Property or their Designee:

Date:

